

## Under Review Notification

**Raised By:** Steven Drouin

**Product #:** D350-689

**Date:** 19.08.12

**Product Name:** DUEL HIGH BACK SEAT INSTALLATION

Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143) (eg. RBEM324U3010101-1)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	"Y" or "N" Required for Each Part Do not leave blank							Reserved ECN / URF Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
		DO NOT SHIP	Red Tag/Quarantine Stock	Advise Customers	Hold all Production	Re-Work Stock	IPP Under Review (Engineer Signoff Required.)	Put Product Specifications Under Review ("Bluefiles")		
DSI9419	IIN-D350-689 Rev. D	Y	N	N	N	N	Y	Y	19-847	Update DSI

**Description of Issue:**

DSI need to be reviewed to fix parts list

<b>Distribution:</b>	VP Operations Director of Operations Director Quality Assurance QC Coordinator	Director of Engineering Chief Engineer Engineering Project Managers Engineering Clerk	Customer Support Manager Production Engineers Production Planners Purchasing Manager	Technical Support Product Manager - Solutions Provider Supply Chain Director / Senior Buyer Marketing Eugene
----------------------	---	--	---	---